Inspection Report




Inspection #56275039 Inspection Cards: 20	Inspected Items: 20 Repo	rted as: PASSED	
Form Outbound - Box Trucks	Inspection Date (Local time) Thu, Jan 9, 2025 11:05 A		
Company U-COOL Refrigeration, LLC	Inspected by Tim Medved	Team U-COOL Refrigeration, LLC	
Asset Name # 826002 26' Truck	Year Make n/a n/a	Model n/a	
VIN n/a	License Plate n/a		
Inspection GPS Location	Submitted Submitted E Odometer	Submitted Engine Hours	
47.241779392932 -122.41654264136	244,079 mi 6,979 hrs		
Total Defects: 0	▲ New: 0 ල In Progres	ss: 0	

✓ Corrected: 0

1	U-COOL Customer Name	
1.1	For Sale Dept	Data Entry
2	Enter Mileage out	
2.1	244079	Mileage
3	Fuel level - Out	
3.1	F	Data Entry
4	DEF Level Out	
4.1	F	Data Entry
5	Reefer engine hours	
5.1	6979	Engine Hours
6	Reefer Meter - Electric Hours out	
6.1	2	Data Entry
7	Set temperature going out	

7.1	34	Data Entry	
8	List Additional Accessories sent out		
8.1	0	Data Entry	
9	Picture of ROOF		
9.1	-	Photo	
	Photos		
10	Picture of Front		
10.1	-	Photo	
	Photos		
	THERMOKING CONTRACTION OF CONTRACTION OF		
11	Windsheild		

11.1	-	Photo	
	Photos		
12	Picture of Passenger Side		
12.1	-	Photo	
13	Picture of Rear		
13.1	-	Photo	
	<section-header><section-header><section-header></section-header></section-header></section-header>		
14	Picture of Driver's Side		



16.1	-	Photo	
	Photos		
17	Comments		
17.1	0	Data Entry	
18	Picture of driver's license		
18.1	-	Skip	
19	Picture of where delivered.		
19.1	-	Skip	
20	Customer Signature - Please sign		
20.1	-	Signature	
	Operator's Signature		
	Operator Tim Medved 09 Jan 2	025 11:05 AM	

Signatures	
Reporting Operator's Signature Tim Medved 09 Jan 2025 11:05 AM	Reviewing Operator's Signature n/a
TM	Condition of the above asset is satisfactory